## CERTIFICATE OF COMPLIANCE

 Certificate Number
 20190218-E327489

 Report Reference
 E327489-20190219

 Issue Date
 2019-FEBRUARY-18

Issued to: OBO BETTERMANN Holding GmbH & Co. KG

**Hueingser Ring 52** 

58710 Menden GERMANY

This certificate confirms that representative samples of

**COMPONENT - SURGE-PROTECTIVE DEVICES** 

Series: MCF

Cat No. MCF100-3-NPE+FS, MCF75-3+FS

Have been investigated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete

in certain constructional features or restricted in

performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

Standard(s) for Safety: UL 1449 Standard for Surge Protective Devices

CSA C22.2 No. 269.4 Surge Protective Devices – Type 4 –

Component Assemblies

CSA C22.2 No. 269.5 Surge Protective Devices – Type 5 –

Components

Additional Information: See the UL Online Certifications Directory at

https://ig.ulprospector.com for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.

Bruce Mahrenholz, Director North An

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, pleas contact a local UL Customer Service Representative at <a href="http://ul.com/aboutul/locations/">http://ul.com/aboutul/locations/</a>

(U)